


ISSUE:	DRAWN BY:	CHECKED BY:	CRF No:	DATE:	DESCRIPTION:
a	SJ	KB	2758	02/08/22	First Issue
b	MK	KB	2950	09/05/23	Replaced SA393 with SA460 and replaced SA070 with KLS2
c					
d					
e					
f					
g					
h					
i					
j					
k					
l					
m					



TA3PR/FL KammBar

Instructions




CITY CRASH (✓)


According to ISO/ PAS 11154:2006




KammBar Pro & Black




KammBar Fleet




Fitting Kit




1.



2.




3.




SA397

PS176




SA397

PS178




SA397

PS176




SA398




PS176

SA398




PS178

SA398



PS176


4.



PS176

PS023

5.



PS178

PS023

